

## Challenge

### Issue

The pump performed inefficiently, and increased downtime and maintenance. It had been treated biannually with a combo of cathodic protection and coal tar epoxy coating.

### Goal

Provide 6 year's of service life to the main seawater cooling pump.

### Root Cause

Severe corrosion at bottom part of the pump, bell housing, and diffuser vanes.

## Solution

### Preparation

- Remove remainder of coal tar epoxy coating
- Grit blast to Sa 2.5 with 3 mil (75 µm) angular profile

### Application

1. Repaired and rebuilt severe corrosion pitting using **ARC 858**
2. Three coats of **ARC 855** with DFT of 14 mils (350 µm) per coat

## Results

### Service Life Since Coating with ARC

- 18 years

### Client Reported Cost Avoidance:

- A new pump, estimated: DKK 6M (€ 800K)

### Client Estimated Maintenance Savings

Elimination of pump disassembly and biannual coating assessed at: DKK 1M (€ 130K)


**Total Savings in 18 years DKK 7M (€ 930K)**



*Pump diffuser after removal of old coal tar epoxy coating*



*Completed application of ARC 858 and ARC 855 to all the wet end pump components*



*Inspection after 18 years service revealed the ARC 855 coating still to be in excellent condition*