

## Challenge

### Issue

Previously applied coating had failed after 2 years, resulting in severe pitting and weld zone corrosion. Client was forced to replace 10% of floor plate at cost of €175K. 40% of floor experienced pitting corrosion up to 30% of plate thickness.

### Goal

Restore tank to avoid extensive plate replacement.

### Root Cause

Prior failed lining and corrosive effects of seawater.



Severe pitting corrosion found under the existing coating repaired with ARC 858

## Solution

### Preparation

- Plate replacement in 10% of surface area
- Grit blast to Sa 2.5 with 3 mil (75 µm) angular profile

### Application

1. Corroded and pitted areas were brought back to 100% of original thickness with **ARC 858**
2. Use **ARC S1** to stripe coat weld seams, striker plates, and transition points
3. Apply 2 coats of **ARC S1** via heated plural component spray equipment to a total DFT of 20 mils (500 µm)



Application of the stripe coat to all weld seams

## Results

### Client Reported

The ARC lining is still protecting the tank after 5 years.

### Client Reported Savings

■ Plate repair, weld repair	€1,750,000
■ Previous lining	€ 150,000
<b>Total</b>	<b>€ 1,225,000</b>
■ <b>Plate repair and ARC lining</b>	<b>-€ 375,000</b>
<b>Savings</b>	<b>€ 850,000</b>



Final inspection of the ARC lining to ensure a continuous pinhole free protective lining