

## Challenge

### Issue

Reduced MTBR of cyclones required wear plate replacement every 4-5 months. Each repair took 4 days to complete, resulting in 288 hours lost production.

### Goals

- Increase MTBR by 2X
- Reduce lost production

### Root Cause

Sinter flow at high velocity and temperature wore weld overlay.

## Solution

### Preparation

- Remove contaminants
- Grit blast to Sa 2.5 with 3 mil (75 μm) angular profile

### Application

- Trowel apply **ARC BX1\*** 6-8 mm (.25"-.3") DFT to the internal surfaces of the cyclone

*\*ARC BX1 is the "Bulk" package size of ARC 890*

## Results

### Client Reported

Minimal repairs required at 11 month inspection. In general <15% of lining thickness lost. All repairs completed within 24 hours.

### Savings

- MTBR was increased to 3 years
- ARC solution saved >2,000 hours downtime over 36 months
- Production and maintenance costs dramatically reduced



Severe abrasive wear typically repaired by welding in new wear plates every 4-5 months



Application of ARC BX1\* in one of the cyclones at 6-8 mm



After 11 months in service minimal wear is seen to the ARC BX1\*